



U.S. Department of
Transportation

**Federal Motor
Carrier Safety
Administration**

1200 New Jersey Ave., S.E.
Washington, DC 20590

December 22, 2011

In reply refer to:
USDOT No.: 1797308

EDUARDO NASCINETO
SAFETY DIRECTOR
CARLOS JOSE PEREZ LAGOS
FIVE STARS TRUCKING
18333 ROE HAMPTON DRIVE #411
DALLAS, TX 75252

Action Required: Demand for Written Response

Records maintained by the Federal Motor Carrier Safety Administration (FMCSA) indicate that CARLOS JOSE PEREZ LAGOS has committed one or more of the actions listed in 49 CFR section 385.308. In accordance with 49 CFR section 385.308(d), CARLOS JOSE PEREZ LAGOS is hereby advised that CARLOS JOSE PEREZ LAGOS's USDOT New Entrant registration will be **REVOKED AND CARLOS JOSE PEREZ LAGOS WILL BE FORBIDDEN TO OPERATE COMMERCIAL MOTOR VEHICLES IN INTERSTATE COMMERCE on January 24, 2012** unless CARLOS JOSE PEREZ LAGOS submits a written response demonstrating immediate corrective action of the violations listed below. **CARLOS JOSE PEREZ LAGOS must submit this written response WITHIN 30 DAYS OF THE SERVICE DATE OF THIS LETTER.**

VIOLATION 7

49 CFR section 385.308(a)(7) - During the 90 days prior to 12/22/2011, the carrier operated the following commercial vehicles with a driver or vehicle out-of-service rate of 50% or more based on at least three inspections:

INSPECTION DATE	REPORT STATE NUMBER	LICENSE PLATE NUMBER	DRIVER'S LAST NAME
12/16/2011	MOA3E1015401	RL8L37 TX	(b)(6); (b)(7)(C)

CARLOS JOSE PEREZ LAGOS's written response should:

1. Include a copy of this letter;
2. Address each violation listed above;
3. Identify why the violation(s) were permitted to occur;
4. Explain actions taken to correct the violation(s) and include evidence and supporting documentation demonstrating the corrective action;
5. Describe actions taken (e.g., implementation of new policies, procedures, etc) to ensure that the violation(s) will not reoccur in the future.

CARLOS JOSE PEREZ LAGOS's response must be submitted within 30 calendar days from the date of this letter to:

SOUTHERN SERVICE CENTER
1800 CENTURY BOULEVARD, SUITE 1700
ATLANTA, GA 30345
Email: SSCAP@DOT.GOV
Phone: 404-327-7351
Fax: 877-547-0380

Failure to respond to this Demand for Written Response as required and within the time specified

will result in the revocation of CARLOS JOSE PEREZ LAGOS's USDOT New Entrant registration, and CARLOS JOSE PEREZ LAGOS's commercial motor vehicle operations in interstate commerce will be placed out-of-service.

Sincerely,

A handwritten signature in black ink, appearing to read "John Van Steenburg". The signature is written in a cursive style with a large, looping "J" and "S".

John Van Steenburg, Director, Office of Enforcement and Compliance